

Inspection Report

Vehicle Information			
VIN	1FMCUOGX4ĐUB94188	Year	2013
Make	Ford	Model	Escape
Engine	2.0L L4	Transmission	Auto
Exterior Color	Grey	Interior Color	Black
Odometer	133444		•

Documentation			
Owners Manual	Okay	Owners Manual Notes	
Maintenance Record	Okay	Maintenance Record Notes	
Vehicle Keys	Okay	Vehicle Keys Notes	
Verify VIN Numbers	Okay	Verify VIN Numbers Notes	

Exterior of Vehicle (Front)			
Front Bumper	Okay	Front Bumper Notes	There are light scratches on the bumper
Front Head Lights	Okay	Front Head Lights Notes	
Fog Lights	Okay	Fog Lights Notes	
Turn Signals	Okay	Turn Signals Notes	
Park Sensors	Okay	Park Sensors Notes	NA
Grille Condition	Okay	Grille Condition Notes	

Front Hood	Okay	Front Hood Notes	There is a small dent
Front End Alignment of Panels	Okay	Front End Alignment of Panels Notes	
Windshield	Okay	Windshield Notes	
Windshield Wipers and Arm	Okay	Windshield Wipers and Arm Notes	

Exterior of Vehicle (Left & Right)			
Fender Alignment and Paint	Okay	Fender Alignment and Paint Notes	The driver's side has a small dent
Marker Lights	Okay	Marker Lights Notes	
A Pillars	Okay	A Pillars Notes	
VIN Plate	Okay	VIN Plate Notes	
Side Mirror Housings/ Glasses	Okay	Side Mirror Housings/ Glasses Notes	
Exterior Door Handles	Okay	Exterior Door Handles Notes	
Door Alignment and Hinge	Okay	Door Alignment and Hinge Notes	
Window Glass	Okay	Window Glass Notes	
Door Seals	Okay	Door Seals Notes	
Side Moldings/ Rocker Panels	Okay	Side Moldings/ Rocker Panels Notes	
B Pillars	Okay	B Pillars Notes	
Window Tream	Okay	Window Tream Notes	
Sill Plate	Okay	Sill Plate Notes	
Child Lock	Okay	Child Lock Notes	
C Pillars	Okay	C Pillars Notes	
Quarter Windows	Okay	Quarter Windows Notes	

Quarter Panels	
Alignment and Paint	

Roof Exterior			
Sunroof Glass and Seal	Okay	Sunroof Glass and Seal Notes	NA
Sunroof Panel	Okay	Sunroof Panel Notes	
Sunroof Antenna	Okay	Sunroof Antenna Notes	
Luggage Rack	Okay	Luggage Rack Notes	
Convertible Top	Okay	Convertible Top Notes	NA

Rear Exterior			
Trunk /Tailgate Paint and Alignment	Okay	Trunk /Tailgate Paint and Alignment Notes	
Rear Window Glass	Okay	Rear Window Glass Notes	
Rear Camera	Okay	Rear Camera Notes	
Trunk Seal	Okay	Trunk Seal Notes	
Luggage Compartment Condition	Requires attention	Luggage Compartment Condition Notes	There is water below the spare. The water is likely leaking through the broken tail lamp
Roadside Kit	Okay	Roadside Kit Notes	
Park Sensors	Okay	Park Sensors Notes	NA
Rear Tail Lights Reverse Hazards and Parking	Requires attention	Rear Tail Lights Reverse Hazards and Parking Notes	The passenger's side taillamp is broken
Turn Signals and Back Lights	Okay	Turn Signals and Back Lights Notes	
License Plate Lights	Okay	License Plate Lights Notes	

Rear Bumper Paint and Alignment	Okay	Rear Bumper Paint and Alignment Notes	There are scratches on the passenger's side
Rear Windshield Wipers and Arm	Okay	Rear Windshield Wipers and Arm Notes	
Bumper Flanges	Okay	Bumper Flanges Notes	

Exterior Summary

Exterior Summary

The vehicle has light scratches and dents

Interior Inspection			
Service Light	Okay	Service Light Notes	
Warning Lights Check	Requires attention	Warning Lights Check Notes	The tire pressure warning light is on
Odors /Mold /Smoke	Okay	Odors /Mold /Smoke Notes	
Horn Operation	Okay	Horn Operation Notes	
Hazard Lights	Okay	Hazard Lights Notes	
Sound System Functionality	Okay	Sound System Functionality Notes	
Speakers	Okay	Speakers Notes	
Bluetooth Functionality	Okay	Bluetooth Functionality Notes	
HVAC /Blower/ Climate Control	Okay	HVAC /Blower/ Climate Control Notes	
Defroster /Defogger	Okay	Defroster /Defogger Notes	
Heater /Seat /Steering	Okay	Heater /Seat /Steering Notes	
Window Switches	Okay	Window Switches Notes	
Wiper Switches/ Washer Pump	Okay	Wiper Switches/ Washer Pump Notes	

Cup Holder	Okay	Cup Holder Notes	
Center Console	Okay	Center Console Notes	
Parking Brake	Okay	Parking Brake Notes	
Sun Visors	Okay	Sun Visors Notes	
Headliner	Okay	Headliner Notes	
Seats Upholstery	Okay	Seats Upholstery Notes	There are small cigarette burns
Seat Functionality	Okay	Seat Functionality Notes	
Interior Trim	Okay	Interior Trim Notes	
Carpeting and Floor Mats	Okay	Carpeting and Floor Mats Notes	

Interior Summary

Interior Summary

Engine Compartment & Undercarriage				
Hood Support	Okay	Hood Support Notes		
Paint and Condition In Engine Compartment	Okay	Paint and Condition In Engine Compartment Notes		
Engine Compartment Labels	Okay	Engine Compartment Labels Notes		
Condition of Engine Covers	Okay	Condition of Engine Covers Notes		
Brake Fluid Reservoir and Cap	Okay	Brake Fluid Reservoir and Cap Notes		
Brake Master Cylinder /Booster	Okay	Brake Master Cylinder /Booster Notes		
Engine Air Filter	Okay	Engine Air Filter Notes		
Accessory Belts Condition	Okay	Accessory Belts Condition Notes	There is sticker indicating the timing belt was replaced	

Engine Gasket /Seals	Okay	Engine Gasket /Seals Notes	
Engine Oil Leaks	Requires attention	Engine Oil Leaks Notes	There is some oil seepage on the belt side of the motor
Radiator and Coolant Hoses	Okay	Radiator and Coolant Hoses Notes	
Water Pump/ Thermostat	Okay	Water Pump/ Thermostat Notes	
Coolant Fan	Okay	Coolant Fan Notes	
Coolant Oil Leaks	Okay	Coolant Oil Leaks Notes	
Power Steering Pump /Hoses	Okay	Power Steering Pump /Hoses Notes	NA
Power Steering Leaks	Okay	Power Steering Leaks Notes	NA
AC Compressor /Lines Condenser	Okay	AC Compressor /Lines Condenser Notes	
Shruts, Shocks and Springs	Okay	Shruts, Shocks and Springs Notes	
CV Joints and Axles	Okay	CV Joints and Axles Notes	
Control Arms	Okay	Control Arms Notes	
Ball Joints and Tie Rod	Okay	Ball Joints and Tie Rod Notes	
Exhaust Pipes	Okay	Exhaust Pipes Notes	
Differential Leaks	Okay	Differential Leaks Notes	
Deformities /Frame Damage	Okay	Deformities /Frame Damage Notes	

Engine Compartment & Undercarriage Summary

The exhaust heat shield is damaged.

Engine Oil	Okay	Engine Oil Notes	
Transmission Fluid	Okay	Transmission Fluid Notes	NA
Engine Coolant	Okay	Engine Coolant Notes	
Power Steering	Okay	Power Steering Notes	NA
Brake Fluid	Requires attention	Brake Fluid Notes	The fluid is dark a fluid flush is needed
Washer Fluid	Okay	Washer Fluid Notes	

Test Drive			
Starter Operation	Okay	Starter Operation Notes	
Engine Performance Idle /Noise /Vibration	Okay	Engine Performance Idle /Noise /Vibration Notes	
Acceleration/ Deceleration	Okay	Acceleration/ Deceleration Notes	
Wheel Bearing Noise	Okay	Wheel Bearing Noise Notes	
Wheel Vibration/ Noise	Okay	Wheel Vibration/ Noise Notes	
Transmission Shifting	Okay	Transmission Shifting Notes	
Transmission/ Transaxle	Okay	Transmission/ Transaxle Notes	
Exhaust Noise/ Odor	Okay	Exhaust Noise/ Odor Notes	
Brake Operation/ Pulsation	Okay	Brake Operation/ Pulsation Notes	
Steering /Tracking /Pulling /Play in the Wheel	Okay	Steering /Tracking /Pulling /Play in the Wheel Notes	Wheel alignment is recommended with tire replacement for maintenance
Suspension Performance	Okay	Suspension Performance Notes	

Drive Assist Functions	Okay	Drive Assist Functions Notes	
HVAC Operation	Okay	HVAC Operation Notes	

Test Drive Summary		
Test Drive Summary		

Scan Tool Diagnostics			
Emission Status	Okay	Emission Status Notes	7 out of 8 of the emission bits are set. The evaporative system is still pending
Diagnostic Faults Codes	Okay	Diagnostic Faults Codes Notes	

Battery and Charge voltage (V)			
Engine & Ignition Off	12.3	Running	13.9

Left Front Wheel			
Wheel ConditionWheel BrandKelly Edge			
Tire Size	235/55R17	Wheel Tread Depth	5/32
Wheel Pressure	36	Wheel Notes	

Left Rear Wheel				
Wheel ConditionThe rear tires are crackingWheel BrandWinrun				
Tire Size	235/55ZR17	Wheel Tread Depth	5/32	
Wheel Pressure	36	Wheel Notes		

Right Front Wheel			
Wheel Condition		Wheel Brand	Kelly Edge

Tire Size	235/55ZR17	Wheel Tread Depth	5/32
Wheel Pressure	36	Wheel Notes	

Right Rear Wheel					
Wheel Condition	The rear tires are cracking	Wheel Brand	Winrun		
Tire Size	235/55ZR17	Wheel Tread Depth	5/32		
Wheel Pressure	36	Wheel Notes			

Spare Wheel					
Wheel Condition		Wheel Brand	Maxxis		
Tire Size	155/70D17	Wheel Tread Depth	4		
Wheel Pressure		Wheel Notes			

Brake Pad Measurements (mm)					
Driver Front	3	Passenger Front	3		
Driver Rear	3	Passenger Rear	3		

Car Pro Inspections